


INSTALLATION AND MAINTENANCE MANUAL

SELF-REGULATING HEATING CABLE SYSTEMS




1	General information	Pg. 3
2	Heating cable selection	Pg. 5
3	Heating cable installation	Pg. 5
4	Components installation	Pg. 13
5	Thermostats	Pg. 18
6	Thermal insulation and marking	Pg. 19
7	Power supply and electrical protection	Pg. 21
8	Heating cable testing	Pg. 21
9	Operation, maintenance and pipe repairs	Pg. 23
10	Heating cable damage	Pg. 24
11	Troubleshooting guide	Pg. 24

GENERAL INFORMATION

The Installation and Maintenance manual is for nVent RAYCHEM self-regulating and power limiting heating cable systems on thermally insulated pipes and vessels only. For information regarding other applications contact your nVent representative.

BTV & XTV Self Regulating Heating Cables



- Power output varies with temperature. As pipe temperature increases, power output decreases.
- At high temperatures, the polymer expands, reducing the number of the conductive paths, and thus reducing current flow.
- At low temperatures, there are many conductive paths, allowing current to flow between the conductors.

Important

For the nVent warranty to apply, the instructions that are included in this manual and product packages must be followed. The installation must be compatible with local requirements applicable to electric heat-tracing systems.

EAC	Certificate No	Marking
		1Ex e IIC T6 Gb X
BTV	TC RU C-BE.MIO62.B.00054/18	1Ex e mb IIC T6 Gb X
BIV	000 "ПРОММАШ ТЕСТ"	Ex tb IIIC T80°C Db X
		Ex tb mb IIIC T80°C Db X
		1Ex e IIC T* Gb X
VTV	TC RU C-BE.MIO62.B.00054/18	1Ex e mb IIC T* Gb X
XTV	000 "ПРОММАШ ТЕСТ"	Ex tb IIIC T* Db X
		Ex tb mb IIIC T* Db X

	BTV	XTV
Minimum Bending Radius		
-60°C ≤ T < -20°C	35 mm	51 mm
-20°C ≤ T < -10°C	30 mm	35 mm
-10°C ≤ T < 0°C	25 mm	25 mm
0°C ≤ T < +10°C	20 mm	20 mm
T ≥ +10°C	12 mm	12 mm
Minimum Installation Temperature	-60°C	-60°C

	BTV	XTV
Maximum Maintain Temperature (power on)	65°C	120°C
Maximum Exposure Temperature (1000 hrs cumulative exposure power on)	85°C	250°C (*)
Maximum Exposure Temperature (continuous power off)	_	-
Self-limiting Temperature in accordance with EN62086-1 5.1.11	Т6	T3 (T2: 20XTV2)
Power Limiting Temperature (*By design)	_	T*
(*) The 250°C rating applies to all product	e printed "MAY SHOP	T-TEDM EXPOSITE

^(*) The 250°C rating applies to all products printed "MAX SHORT-TERM EXPOSURE 2500".

Warning

As with any electrical equipment or wiring installation operating at line voltages, heating cable and component damage or incorrect installation that allows the penetration of moisture or contamination can lead to electrical tracking, arcing and potential fire hazard.

Do not connect heating cable conductors together or this will result in a short circuit.

Any unconnected heating cable end must be sealed with a nVent approved end seal.

To prevent fire or explosion in hazardous areas, verify that the maximum sheath temperature of the heating cable is below the auto-ignition temperature of the gases in the area. For further information, see design documentation.

HEATING CABLE SELECTION 2

Check the design specification to make sure the proper heating cable is installed on each pipe or vessel. Refer to nVent product literature and the TraceCalc software to select the proper heating cable for each thermal, chemical, electrical and mechanical environment.

3 HEATING CABLE INSTALLATION

Warning

De-energise all power circuits before installation or servicing

Heating cable storage

- Keep ends of heating cable and kit components dry before and during installation
- Temperature range: -40°C to +60°C
- Protect the heating cable from mechanical damage

Storage and transportation of the heating cable should be carried out in accordance with GOST 18690-82

3.2 Pre-installation checks

Check materials received:

- Review the heating cable design and compare the list of materials to the catalogue numbers of heating cables and electrical components received to confirm that proper materials are on site. The heating cable type is printed on its outer jacket.
- Temperature exposure must not exceed that specified in nVent product literature. Exceeding these limits will impair product performance. Check that expected exposure is within these limits.
- Ensure that the heating cable voltage rating is suitable for the service voltage available.
- Do not energize cable when it is coiled or on the reel.
- Inspect heating cable and components for in-transit damage. An insulation resistance test (see section 8) on each reel is recommended.

Check piping to be traced:

- Ensure all pressure testing is complete and pipework has final paint coating.
- Walk the system and plan the routing of the heating cable on the pipe.
- Check pipework against specification drawing. If different consult design authority.
- Inspect piping for burrs, rough surfaces, sharp edges etc. which could damage the heating cable. Smooth off or cover with layers of glass cloth tape or aluminium foil.

3.3 Heating cable handling

Heating cable handling tips:

- Paint and pipe coatings must be dry to the touch before heating cable installation.
- · When pulling the heating cable, avoid:
 - sharp edges
 - excessive pulling force
 - kinking and crushing
 - walking on it, or running over it with equipment

Heating cable pulling tips:

- Use a reel holder that pays out smoothly with little tension.
- Keep heating cable strung loosely but close to the pipe being traced to avoid interference with supports and equipment.
- Pay out designed length and mark (i.e. with fixing tape) on cable while still on reel.
- Leave the appropriate amount of heating cable at all power connection, splice, tee and end seal locations. (Refer to component installation instructions)
 - Add additional heating cable to trace the fittings and supports or for spiralling as required by the design specifications, or consult nVent product literature for design.
- Protect all heating cable ends from moisture, contamination and mechanical damage or other interference if left exposed before component installation.

3.4 Heating cable attachment recommendations

- The heating cable may be installed straight, spiralled or in multiple runs as required by the design specification, nVent product literature or TraceCalc software.
 - Do not use metal attachments, vinyl electrical tape or duct tape as heating cable damage may result.
 - Self-Regulating technology allows for the multiple overlapping of the heating cable on to itself.
- Fix in place with a minimum of two wraps the appropriate self-adhesive glass cloth tape (see figure 1) or plastic cable ties at 300 mm intervals and additionally where necessary.
- Plastic cable ties must have a temperature rating that matches the system exposure temperature.
- The heating cable's minimum bend radius must not be exceeded (refer to p. 2)

Bend the cable only in upright position




The heating cable does not bend easily in the flat plane. Do not force such a bend, as the heating cable may be damaged.

3.4.1 Straight tracing

- Straight trace the pipe unless the design calls for spiralling (see 3.4.2).
- On horizontal pipes fix on lower quadrant as shown in Figure 1 and not on bottom of pipe.
- To prevent overheating, be sure the location of the power limiting heating cable is planned so that the active heating zone will not extend into the component. Read the kit installation instructions and plan the component location before permanently attaching the cable to the pipe. Ensure that the active heating zones are located where heat is required i.e. on the pipe.
- Thermally insulate and weatherproof to specification.


Figure 1



nVent attachment tapes:

GT66 Self-adhesive glass cloth tape General purpose tape. Not for stainless-steel surfaces or for installation temperatures <4°C.

Figure 2



ATE-180 Aluminium tape
Use only if the design requires it.
ATE-180 improves the heat transfer and increases the power output of the heating cable.
Attach the heating cable to the pipe as shown in Figure 2.

3.4.2. Spiral tracing

- Alternative spiralling methods are shown in Figures 2a and 2b.
- · Only spiral heating cable on pipe when called for by design.
- To prevent overheating, be sure the location of the power limiting heating cable is planned so that the active heating zone will not extend into the component. Read the kit installation instructions and plan the component location before permanently attaching the cable to the pipe. Ensure that the active heating zones are located where heat is required i.e. on the pipe.


Spiral Pitch Table (mm).

NB	NPS	Spiral	Ratio			
(mm)	(inches)	Metres	of cable p	er metre	of pipe	
		1.1	1.2	1.3	1.4	1.5
25	1	250	170	140	110	100
32	11/4	310	210	170	140	130
40	11/2	350	240	190	160	140
50	2	430	300	240	200	180
65	21/2	520	360	290	240	210
80	3	630	430	350	290	260
90	31/2	720	490	390	330	290
100	4	800	560	440	370	330
125	5	990	680	550	460	400
150	6	1180	810	650	550	480
200	8	1520	1050	840	710	620

Example:

For pipe of 80 mm NB (3" NPS) requiring 1.3 metres of heating cable per metre of pipe, pitch is 350 mm.


Figure 2a



Heating cable length = pipe length x spiral ratio Refer to design specification for spiral ratio

- Step 1 Make starting loop as shown
- Step 2 Grasp loop and wind around pipe
- Space evenly and attach to pipe. Step 3 Thermally insulate and weatherproof to specification

Figure 2b



Refer to design specification for spiral pitch

Mark the pipe at the spiral pitch or use a simple length gauge

Fix the heating cable as installation progresses

Thermally insulate and weatherproof to specification

3.5 Cutting the heating cable

- Cut the heating cable to length after it is attached to the pipe. Before cutting it, confirm the tracing allowance as per Sections 3.3 and 3.6.
- RAYCHEM heating cable can be cut to length without affecting the heat output per metre.

3.6 Typical installation details


Typical installation details for fixing heating cable to pipe fittings are shown hereafter.

General notes:

- · Trace pipe fittings as shown to allow easy maintenance.
- Consult the design specification or nVent product literature or TraceCalc software for the tracing requirements for fittings and supports.
- Follow the recommendations for cutting and stripping heating cables; they are included in the component installation instructions.

3.6.1 Valve


Figure 3



- Refer to design specification for additional heating cable length.
- · Fix with self-adhesive glass cloth tape.
- Thermally insulate and weatherproof to specification (including valve stem).

3.6.2 Elbow


Figure 4



- Fix heating cable to outside (long) radius of elbow
- Fix with self-adhesive glass cloth tape
- Thermally insulate and weatherproof to specification

3.6.3 Flange


Figure 5



- Additional heating cable is 2-3 times diameter of pipe (typical)
- Fix with self-adhesive glass cloth pipe
- Thermally insulate and weatherproof to specification

3.6.4 Pipe bar hanger

Figure 6




- Do not clamp heating cable with support. Heating cable must be over the support
- No additional heating cable is required for bar or rod pipe hangers unless called for in the design specification, then use loop length specified
- Fix with self-adhesive glass cloth tape Thermally insulate and weatherproof to specification


3.6.5 Pipe support shoe

Figure 7

Side view



View from under



- Refer to design specification for additional heating cable length
- Fix with self-adhesive glass cloth tape
- Thermally insulate and weatherproof to specification

COMPONENTS INSTALLATION

General notes:

Select the required components from nVent product literature or use the TraceCalc software.

RAYCHEM component kits (including power connections, splices and end seals) must be used to satisfy Standards and Approval Body requirements.

Installation instructions included in the kit must be followed, including those for preparation of the heating cable conductors for connections. Before assembly, use the guide given in the instructions to ensure that the kit is correct for the heating cable and environment.


 RAYCHEM self-regulating and power limiting heating cables are parallel circuit design. Do not twist the conductors together as this will result in a short circuit.

4.1 Components required


- For the installation of all components refer to the relevant component installation instructions.
- Required for each heating cable run: Power connection and insulation entry kit Fnd seal.
- As required: Splice. Tee-splice. Junction box. Three connection kits and three insulation entry kits. Accessories (pipe straps, fixing tape, support brackets, labels, etc.).

4.2 Typical systems

Figure 8a




14 | nVent.com nVent.com | 15



16 | nVent.com | 17

4.3 Component installation hints

- On horizontal pipes locate junction boxes below pipe wherever possible. Pinch out drainhole in the stand when installing upside down.
- Locate junction boxes for easy access but not exposed to mechanical abuse.
- Position junction boxes so that power cable and heating cable entries do not point upwards.



- · Fix lids in place where access not required.
- Confirm junction box stopping plugs are correct for application and fixed firmly in place.
- Route heating cable from junction box to insulation entry so as to avoid possible mechanical damage.
 - Do not strain heating cable as it exits/enters junction boxes and insulation entries.
- Ensure heating cable is fixed above pipe straps such as used for junction box support brackets.
- Fix all low profile components (e.g. heatshrink end seals) in place with self-adhesive glass cloth tape.

5 THERMOSTATS

- In temperature-sensitive applications, thermostatic control may be necessary. If maximum temperature is a concern, consult your nVent representative for design assistance.
- Follow the installation instructions supplied with the thermostat. Use the proper wiring diagram for the heating cable layout and control method desired.

THERMAL INSULATION AND MARKING 6

6.1 Pre-insulation checks


- Visually inspect the heating cable and components for correct installation and damage. (See Section 10 if damaged.)
- Insulation resistance (Megger) testing (as per Section 8) is recommended prior to covering the pipe with thermal insulation.


6.2 Insulation installation hints

- Correct temperature maintenance requires properly installed and dry thermal insulation.
- Thermally insulate and weatherproof to design specification.
- Check insulation type and thickness against the design specification.
- To minimize potential heating cable damage, insulate as soon as possible after tracing.
- Check that all pipework, including fittings, wall penetrations and other areas, have been completely insulated.
- Ensure that heating cable is not damaged during installation of cladding for example by drills, self tapping screws and sharp edges of cladding.
- Check that all insulation entry kits are fitted correctly and sealed.
- Ensure that all places where valve stems, support brackets, thermostat capillaries, etc exit the cladding are sealed.


6.3 Marking

 For power limiting heating cable install label: LAB-I-35 as shown (typical) in figures 10a & 10b





- The presence of the heating cables shall be made evident by the posting of warning labels or caution labels ("Electric Traced") on the cladding. Labels are to be applied at maximum 3 meter intervals and on alternate locations along the circuit.
- Install "Electric Traced" signs along piping at suitable intervals
 (3 m intervals recommended) on alternate sides as a warning.
- Mark on outside of insulation the location of heating cable components.
- For XTV and KTV heating cables if T-class compliance was proven by stabilized design: install LAB-EX-XTV-KTV aluminium tag at approximately 75 mm from the entry of the junction box.



7 POWER SUPPLY AND ELECTRICAL PROTECTION

7.1 Electrical loading

Size overcurrent protective devices according to the design specification or applicable nVent product literature. If devices other than those specifically identified are used, consult the nVent representative for the appropriate sizing information.

7.2 Ground fault equipment protection is required for each circuit

The metal sheath/braid of the heating cable must be connected to a suitable earthing terminal

7.3 Residual current (earth fault) protection

nVent insists on the use of a 30 mA residual current device to provide maximum safety and protection. However, where there is a marked increase in nuisance tripping, a maximum 300 mA residual current device may be used. For heating cables installed in a hazardous area, the use of residual current devices is normally a condition of their approval.

8 HEATING CABLE TESTING

8.1 Recommendations


nVent recommends insulation resistance test before installing heating cable; before installing thermal insulation; prior to initial start-up; and as part of the periodic maintenance. (see Section 9.2).

8.2 Test method

After completing heating cable installation, the insulation resistance between the conductors and the braid should be checked (see Figure 11) using a 2.500 VDC megger. Minimum readings should be 10 Megohms regardless of the heating cable length. The installer should record the original values for each circuit on the installation record sheet (see page 25). If a thermostat is installed, it should be bypassed.

Figure 11

Test between heating cable and braid



9 OPERATION, MAINTENANCE AND PIPE REPAIRS

9.1 Heating cable operation

- Temperature exposure must not exceed that specified in nVent product literature. Exceeding those limitations will shorten the service life and may permanently damage the heating cable.
- Pipe insulation must be complete and dry to maintain the correct temperature.

9.2 Inspection and maintenance

- Visual inspection: Exposed heating cable and pipe insulation should be checked periodically to make sure that no physical damage has occured.
- Meggering: The system should be meggered regularly. When
 meggering the insulation resistance from the main supply
 panel, it is recommended that the test is performed between
 L/N (together) and PE. Freeze protection systems should be
 meggered before the winter months each year (see section
 8). Temperature maintenance systems should be tested at
 least twice a year. Function testing of electrical protection
 and temperature control systems should be carried out at
 regular intervals.
- The Periodic Inspection Record on the following pages should be filled out during maintenance of each circuit in your system.

9.3 Piping systems repair and maintenance

- Isolate heating cable circuit.
- Protect the heating cable from mechanical or thermal damage during pipe repair work.
- Check heating cable installation after pipe repairs and restore thermal insulation following the recommendations in Section 6. Check correct functioning of electrical protection systems.

10 HEATING CABLE DAMAGE

- Do not repair damaged heating cable.
 Remove entire damaged section and splice in a new length using the appropriate RAYCHEM splice kits.
- Replace damaged heating cable at once.
 Damage allowing moisture and contamination to enter the heating cable may result in arcing earth faults and potential fire hazards.
- Heating cable exposed to fire or flame may cause further fire damage if powered.
 Remove from service at once and replace before re-use.

11 TROUBLESHOOTING GUIDE

Refer to the Troubleshooting guide on pages 32-34.
 If the problem persists after following the guide procedures, contact your nVent representative immediately.

		INSTAL	INSTALLATION RECORD SHEET	ECORD SHI	EET		
		ON LINDUIL					
INSTALLATION RECORDS FOR:							
Circuit breaker number							
Drawing reference number							
Megger test on pipe before insulating	Reading						
(bypass thermostat if applicable)							
	Date						
Megger test after insulating (bypass	Reading						
thermostat if applicable)	Initial						
	Date						
Circuit voltage	Panel						
	Connection terminals						
Insulation complete and sealed	Initial						
	Date						
Locations of low profile components	Initial						
are marked on the cladding	Date						
REMARKS & COMMENTS:							

	INSPEC	TION AND	MAINTEN	INSPECTION AND MAINTENANCE RECORD SHEET	ORD SHEET		
	"IOUIO	CIPCUIT NO.					
MAINTENANCE CHECKS FOR:				MONTH:		YR.:	
No signs of overheating, moisture, or corrosion, etc.	Initial						
	Date						
In connection systems Heating cable and cable glands tight Connection terminals tight	Initial						
Earth connection tight Insulation in good condition	Date						
Thermostats set properly and capillaries are protected	Initial						
	Date						

Megger test (bypass thermostat if applicable)	Reading				
	Initial				
	Date				
Circuit voltage	Panel				
	Connection terminals				
All boxes and thermostats have been Initial firmly closed	Initial				
	Date				
Locations of low profile components are marked on the cladding	Initial				
	Date				

REMARKS & COMMENTS:

Troubleshooting guide Α Symptom: Overcurrent protection trips or blows Probable Causes Electrical fault at a damaged heating cable b faulty splices or tees c end seal d connection Circuit oversized Start-up below design temperature 3 Defective electrical protection Symptom: RCD trips В Probable Causes Earth fault at: a damaged heating cable b faulty splices or tees end seal С connection Excessive moisture in: 2 a junction boxes b splices and tees c end seals High leakage currents due to a combination 3 of excessive lengths of power cable and heating cable. Mains borne disturbances 5 Defective RCD

28 | nVent.com

C 1	Corrective Actions Investigate and remedy (see note 1):
2	Resize or redesign within Technical Databook Guidelines. (If larger protection is required, ensure supply cables are compatible).
3	 a redesign for lower start-up temperatures b preheat pipe from alternative heat source to within exposure temperatures given in Product Data Sheets c Energize part of circuit followed by remainder (e.g. in sequence
4	Replace
C	Corrective Actions
1	Investigate and remedy (see note 1):
2	Dry out and reseal or remake immediately. Perform insulation resistance test. (10 MΩ minimum)
3	Redesign
4	Redesign distribution, guidance is available from nVent
5	Replace

С	Symptom: No power output. Probable Causes
1	Loss of supply voltage due to: a overcurrent or residual current protection operating b loose terminals in junction box c loss of supply cable continuity (e.g., open circuited from damage
2	Control thermostat is connected in the normally open position
3	High resistance connection at: a junction box terminals b splices and tees
D	Symptom: Low pipe temperature. Probable Causes
1	Wet thermal insulation
2	Design error
3	Incorrect setting or operation of controls e.g., thermostats.
4	Heating cable has been exposed to excessive temperature beyond rating.
Not	e:

- Visually inspect the power connections, splices and end seals for correct installation.
- Look for signs of damage at:
 a) Valves, pumps, flanges and supports.
 b) Areas where repairs or maintenance work has been carried out.
- 3 Look for crushed or damaged insulation and cladding along the pipe.

Corrective Actions Restore supply voltage following A and B (page 31) b re-tighten terminals NB: If excessive heating has occured due to high resistance, replace terminals or crimps locate damage and repair 2 Reconnect to normally closed position Locate and remedy by: re-tiahten repair NB: If excessive heating has occured due to high resistance, replace terminals or crimps Corrective Actions Remove and replace with dry insulation of correct specification and ensure complete weatherproofing 2 a check with competent authority for design conditions b modify to meet nVent recommendations

3 Repair or reset to correct level of operation

4 Replace

a) Consult nVent for futher assistance.

If after 1, 2 and 3 above the fault has not been located, then either:

b) Where local practices and conditions allow (e.g., non hazardous areas) isolate one section of heating cable from another by cutting in half and testing (e.g., Insulation Resistance) both halves until general area of damage is found. Remove insulation and expose fault.

Republic of Kazakhstan

Tel. +7 712232 09 68 Fax +7 7122 32 55 54 saleskz@nVent.com

Россия

Тел. +7 495 926 18 85 Факс +97 495 926 18 86 salesru@nVent.com



nVent.com

©2019 nVent. All nVent marks and logos are owned or licensed by nVent Services GmbH or its affiliates. All other trademarks are the property of their respective owners. nVent reserves the right to change specifications without notice.